

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Administration Office	8,094	20	Fair	Good	Good	Good	Good
Alternate School/Weight Room-Calhoun County School	1,700	16	Fair	Fair	Fair	Fair	Fair
Calhoun County High - Portable - Bus Drivers	1,200	20	Poor	Poor	Poor	Poor	Poor
Calhoun County High School	122,164	36	Fair	Good	Good	Poor	Very Good
Sandy Run K-8	95,587	16	Fair	Good	Good	Good	Good
St. Matthews K-8	96,474	15	Poor	Good	Good	Good	Good

[illegible]

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Administration Office	N/A	N/A	Good	Good	N/A	Good	Good
Alternate School/Weight Room- Calhoun County School	N/A	N/A	Fair	N/A	Fair	N/A	N/A
Calhoun County High - Portable - Bus Drivers	N/A	N/A	Poor	N/A	N/A	Poor	N/A
Calhoun County High School	Good	Good	Good	Good	Good	Good	Good
Sandy Run K-8	N/A	Good	Fair	Good	Good	Fair	Good
St. Matthews K-8	N/A	Good	Good	Good	Good	Good	Good

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Administration Office	Good	Good	Good	Good	N/A
Alternate School/Weight Room- Calhoun County School	Good	Good	Good	Good	N/A
Calhoun County High - Portable - Bus Drivers	Poor	Poor	Poor	Fair	N/A
Calhoun County High School	Good	Good	Good	Good	Good
Sandy Run K-8	Good	Good	Good	Good	N/A
St. Matthews K-8	Good	Good	Good	Good	Good

Name of School or Building	Comments on building exterior
Administration Office	
Alternate School/Weight Room- Calhoun County School	
Calhoun County High - Portable - Bus Drivers	The portable exterior is in poor condition The roof needs to be replaced Windows need to be replaced
Calhoun County High School	Visitors and students parking lot has potholes Sidewalks are cracked in several places Back driveway is not paved-crush and run surface
Sandy Run K-8	
St. Matthews K-8	

Name of School or Building	Comments on building accessibility
Administration Office	
Alternate School/Weight Room- Calhoun County School	The area outside building entrance is primary grassy, which would challenge a handicap person.
Calhoun County High - Portable - Bus Drivers	Handicap persons have no excess to the portable
Calhoun County High School	
Sandy Run K-8	
St. Matthews K-8	

Name of School or Building	Comments on building interior finishes
Administration Office	
Alternate School/Weight Room- Calhoun County School	The interior finish requires painting.
Calhoun County High - Portable - Bus Drivers	Walls require painting
Calhoun County High School	
Sandy Run K-8	The brick walls have cracks in many of the classrooms.
St. Matthews K-8	

Name of School or Building	Comments on MEP
Administration Office	
Alternate School/Weight Room- Calhoun County School	
Calhoun County High - Portable - Bus Drivers	Electric needs updating
Calhoun County High School	
Sandy Run K-8	Automatic hand dyers aren't working in the girl's bathroom. The urinals need to be resealed to the walls in the boy's bathroom.
St. Matthews K-8	

Name of School or Building	Comments on building life safety and security
Administration Office	
Alternate School/Weight Room- Calhoun County School	
Calhoun County High - Portable - Bus Drivers	
Calhoun County High School	
Sandy Run K-8	
St. Matthews K-8	

Name of School or Building	
Administration Office	
Alternate School/Weight Room- Calhoun County School	
Calhoun County High - Portable - Bus Drivers	
Calhoun County High School	
Sandy Run K-8	
St. Matthews K-8	