

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Brockington Elementary Magnet School	60,022	63	Good	Good	Good	Good	Good
Brunson-Dargan Elementary School- Library Building	48,843	59	Poor	Fair	Fair	Fair	Fair
Cain Elementary School- Building 1	29,587	64	Good	Good	Good	Good	Good
Cain Elementary School- Building 2	29,587	64	Good	Fair	Fair	Good	Good
Cain Elementary School- Building 3	29,587	64	Good	Good	Good	Good	Good
Cain Elementary School- Building 4	29,587	64	Good	Good	Good	Good	Good
Carolina Elementary School	27,700	68	Good	Good	Good	Good	Good
Darlington County Adult Education Building	95,746	64	New/Less than Not Operational year	Fair	Fair	Fair	Fair
Darlington County Institute of Technology	79,000	10	Very Good	Very Good	Very Good	Very Good	Very Good

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Darlington County Intervention School	47,873	53	Poor	Fair	Fair	Fair	Fair
Darlington High School - Main Building	176,307	40	Fair	Fair	Fair	Fair	Fair
Darlington High School- 9th Grade Building	176,307	40	Fair	Fair	Fair	Fair	Fair
Darlington High School- Band Building	176,307	40	Good	Fair	Fair	Fair	Fair
Darlington High School- Cafeteria Building	176,307	40	Fair	Fair	Fair	Fair	Fair
Darlington High School- Gym	176,307	40	New/Less than Not Operational year	Good	Good	Good	Good
Darlington High School- ROTC Building	176,307	40	New/Less than Not Operational year	Fair	Fair	Fair	Fair
Darlington Middle School	140,000	10	Good	Very Good	Very Good	Very Good	Very Good
Hartsville High School Building 1	199,623	55	Poor	Fair	Fair	Fair	Fair

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Hartsville High School Building 2	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 3	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 4	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 5	199,623	55	Poor	Fair	Fair	Fair	Fair
Hartsville High School Building 6, Cafeteria	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 7	199,623	55	New/Less than Not Operational year	Fair	Fair	Fair	Fair
Hartsville High School Main Office	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville High School, Art Building	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville High School, Band Building	199,623	55	Fair	Fair	Fair	Fair	Fair

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Hartsville High School, Locker Room	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville High School, Main Gym	199,623	6	Very Good	Very Good	Very Good	Very Good	Very Good
Hartsville High School, Ulmer Gym	199,623	55	Fair	Fair	Fair	Fair	Fair
Hartsville Middle School	160,000	10	Good	Very Good	Very Good	Very Good	Very Good
Lamar Elementary School-Building 1	43,100	87	Fair	Good	Good	Good	Good
Lamar Elementary School-Building 2	43,100	87	Good	Good	Good	Good	Good
Lamar High School	77,350	42	Poor	Fair	Good	Fair	Good
Mayo High School	76,204	68	Fair	Good	Fair	Fair	Fair
Mayo High School Annex Building	76,204	68	Poor	Fair	Fair	Fair	Fair

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Mayo High School Building 3	76,204	68	Poor	Fair	Fair	Fair	Fair
Mayo High School Building 4 Cafeteria	76,204	68	Poor	Fair	Fair	Fair	Fair
Mayo High School Building 5	76,204	68	Poor	Fair	Fair	Fair	Fair
North Hartsville Elementary School- Building 1 and 2	66,200	66	Fair	Good	Good	Good	Good
North Hartsville Elementary School- Building 3	66,200	66	Good	Good	Good	Good	Good
Pate Elementary School- Building 1	45,876	61	Fair	Fair	Fair	Good	Fair
Pate Elementary School- Building 2	45,876	61	Fair	Fair	Fair	Good	Fair
Rosenwald Elementary/Middle School	44,946	64	Very Good	Good	Good	Good	Good
Rosenwald Elementary/Middle School- Building 2	44,946	64	Very Good	Good	Good	Good	Good

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Rosenwald Elementary/Middle School- Main Building	44,946	64	Very Good	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 1	30,000	58	New/Less than Not Operational year	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 2	30,000	58	New/Less than Not Operational year	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 3	30,000	58	New/Less than Not Operational year	Good	Good	Good	Good
Spaulding Elementary School	26,400	64	Good	Good	Good	Good	Good
St. John's Elementary School- Building A	130,930	112	Fair	Good	Fair	Fair	Fair
St. John's Elementary School- Building B	130,930	112	New/Less than Not Operational year	Good	Good	Good	Good
St. John's Elementary School- Building C	130,930	112	Fair	Good	Good	Good	Good
Thornwell School for the Arts- Building 3	43,000	98	Good	Good	Good	Good	Good

Name of School or Building	Approximate square footage	Approximate age, years	Roof	Exterior Walls	Exterior Windows	Exterior Accessibility	Exterior Doors
Thornwell School for the Arts- Building 5	43,000	98	Good	Fair	Fair	Good	Fair
Thornwell School for the Arts- Gymnasium	43,000	98	Fair	Fair	Fair	Good	Fair
Thornwell School for the Arts- Main Building	43,000	98	Good	Fair	Fair	Fair	Fair
Washington Street Elementary School	45,500	55	Fair	Good	Good	Good	Good
West Hartsville Elementary School	29,700	61	Good	Good	Good	Good	Good
Brunson-Dargan Elementary School	48,843	59	Poor	Fair	Fair	Fair	Fair
Spaulding Middle School	26,400	64	New/Less than Not Operational year	Good	Good	Good	Good

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessibility	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Darlington County Intervention School	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Darlington High School - Main Building	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Darlington High School- 9th Grade Building	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Darlington High School- Band Building	Fair	N/A	Fair	Fair	Fair	Fair	N/A
Darlington High School- Cafeteria Building	Fair	Fair	Fair	Fair	Fair	N/A	N/A
Darlington High School- Gym	Good	Good	Good	Good	Fair	Fair	Good
Darlington High School- ROTC Building	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Darlington Middle School	Very Good	Very Good	Very Good	Very Good	Very Good	Very Good	Very Good
Hartsville High School Building 1	Fair	Fair	Fair	Fair	Poor	Fair	N/A

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessibility	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Hartsville High School Building 2	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Hartsville High School Building 3	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Hartsville High School Building 4	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Hartsville High School Building 5	Fair	Fair	Fair	Fair	Poor	Fair	N/A
Hartsville High School Building 6, Cafeteria	Fair	Fair	Fair	Fair	Fair	N/A	N/A
Hartsville High School Building 7	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Hartsville High School Main Office	Fair	Fair	Fair	Fair	Fair	N/A	N/A
Hartsville High School, Art Building	Fair	Fair	Fair	N/A	Fair	Good	N/A
Hartsville High School, Band Building	Fair	Fair	Fair	N/A	Fair	Fair	N/A

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessibility	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Hartsville High School, Locker Room	Fair	Fair	Fair	Fair	Poor	N/A	N/A
Hartsville High School, Main Gym	Very Good	Very Good	Very Good	Very Good	Very Good	N/A	Very Good
Hartsville High School, Ulmer Gym	Fair	Fair	Fair	Fair	Poor	Poor	Fair
Hartsville Middle School	Very Good	Very Good	Very Good	Very Good	Very Good	Very Good	Very Good
Lamar Elementary School-Building 1	Good	Good	Good	Good	Good	Fair	N/A
Lamar Elementary School-Building 2	Good	Good	Good	Good	Good	Good	N/A
Lamar High School	Good	Good	Good	Good	Good	Good	Very Good
Mayo High School	Fair	Good	Good	Fair	Fair	Fair	N/A
Mayo High School Annex Building	Fair	Fair	Fair	Fair	Fair	Fair	N/A

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessibility	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Mayo High School Building 3	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Mayo High School Building 4 Cafeteria	Fair	Fair	Fair	Fair	Fair	Fair	N/A
Mayo High School Building 5	Fair	Fair	Fair	Fair	Fair	Fair	N/A
North Hartsville Elementary School- Building 1 and 2	Good	Good	Good	Good	Good	Good	N/A
North Hartsville Elementary School- Building 3	Good	Good	Good	Good	Fair	Good	N/A
Pate Elementary School- Building 1	Good	Good	Good	Good	Good	Good	Fair
Pate Elementary School- Building 2	Good	Good	Good	Good	Good	Good	N/A
Rosenwald Elementary/Middle School	Good	Good	Good	Good	Good	Good	N/A
Rosenwald Elementary/Middle School- Building 2	Good	Good	Good	Good	Good	Good	N/A

Name of School or Building	Building Security	Toilet Room Accessibility	Other Interior Assessibility	Administration Area Condition	Common Area and Corridor Condition	Classroom Condition	Gymnasium Condition
Rosenwald Elementary/Middle School- Main Building	Good	Very Good	Good	Good	Good	Good	N/A
Southside Early Childhood Education Center- Building 1	Good	Good	Good	Good	Good	Good	N/A
Southside Early Childhood Education Center- Building 2	Good	Good	Good	Good	Good	Good	N/A
Southside Early Childhood Education Center- Building 3	Good	Good	Good	Good	Good	Good	N/A
Spaulding Elementary School	Good	Good	Good	Good	Good	Good	N/A
St. John's Elementary School-Building A	Fair	Fair	Fair	Fair	Fair	Fair	Fair
St. John's Elementary School-Building B	Good	Good	Good	Good	Good	Good	N/A
St. John's Elementary School-Building C	Good	Good	Good	Good	Good	Good	N/A
Thornwell School for the Arts-Building 3	Good	Good	Good	Good	Good	Good	N/A

[illegible]

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Brockington Elementary Magnet School	Good	Good	Good	Good	Good	Good	Good
Brunson-Dargan Elementary School- Library Building	N/A	N/A	Fair	Fair	Fair	Fair	Good
Cain Elementary School- Building 1	N/A	Fair	Good	Good	Good	Good	Good
Cain Elementary School- Building 2	N/A	N/A	Good	Good	Good	Good	Good
Cain Elementary School- Building 3	N/A	N/A	Good	Good	Good	Good	Good
Cain Elementary School- Building 4	N/A	N/A	Very Good	Good	Good	Good	Good
Carolina Elementary School	N/A	Good	Fair	Good	Good	Good	Good
Darlington County Adult Education Building	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Darlington County Institute of Technology	Very Good	N/A	Good	Good	Good	Good	Good

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Darlington County Intervention School	Fair	Not Operational	Fair	Fair	Fair	Poor	Fair
Darlington High School - Main Building	N/A	N/A	N/A	Fair	Fair	Fair	Fair
Darlington High School- 9th Grade Building	N/A	Fair	Fair	Fair	Fair	Fair	Fair
Darlington High School- Band Building	N/A	N/A	N/A	Fair	Fair	Fair	Fair
Darlington High School- Cafeteria Building	N/A	Good	Fair	Fair	Fair	Fair	Fair
Darlington High School- Gym	N/A	N/A	Fair	Good	Good	Good	Good
Darlington High School- ROTC Building	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Darlington Middle School	N/A	Very Good	Very Good	Good	Good	Good	Good
Hartsville High School Building 1	N/A	N/A	Fair	Fair	Fair	Fair	Fair

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Hartsville High School Building 2	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 3	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 4	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 5	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 6, Cafeteria	N/A	Good	Fair	Fair	Fair	Fair	Fair
Hartsville High School Building 7	N/A	Good	Fair	Fair	Fair	Fair	Fair
Hartsville High School Main Office	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Hartsville High School, Art Building	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Hartsville High School, Band Building	N/A	N/A	Fair	Fair	Fair	Fair	Fair

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Hartsville High School, Locker Room	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Hartsville High School, Main Gym	N/A	N/A	Very Good	Very Good	Very Good	Very Good	Very Good
Hartsville High School, Ulmer Gym	N/A	N/A	Poor	Fair	Fair	Fair	Fair
Hartsville Middle School	Very Good	Very Good	Very Good	Good	Good	Good	Very Good
Lamar Elementary School-Building 1	N/A	N/A	Good	Good	Good	Good	Good
Lamar Elementary School-Building 2	N/A	N/A	Good	Good	Good	Good	Good
Lamar High School	N/A	Fair	Good	Poor	Poor	Poor	Good
Mayo High School	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Mayo High School Annex Building	N/A	N/A	Fair	Fair	Fair	Fair	Fair

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Mayo High School Building 3	N/A	N/A	Fair	Fair	Fair	Fair	Fair
Mayo High School Building 4 Cafeteria	N/A	Fair	Fair	Fair	Fair	Poor	Fair
Mayo High School Building 5	N/A	N/A	Fair	Fair	Fair	Fair	Fair
North Hartsville Elementary School- Building 1 and 2	N/A	N/A	Good	Good	Good	Good	Good
North Hartsville Elementary School- Building 3	N/A	Good	Good	Good	Good	Good	Good
Pate Elementary School- Building 1	N/A	Good	Good	Good	Good	Good	Good
Pate Elementary School- Building 2	N/A	N/A	Good	Good	Good	Good	Good
Rosenwald Elementary/Middle School	N/A	N/A	Good	Good	Good	Good	Good
Rosenwald Elementary/Middle School- Building 2	N/A	N/A	Good	Good	Good	Good	Good

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Rosenwald Elementary/Middle School- Main Building	N/A	Good	Very Good	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 1	N/A	Good	Good	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 2	N/A	N/A	Good	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 3	N/A	N/A	Good	Good	Good	Good	Good
Spaulding Elementary School	N/A	N/A	Fair	Fair	Poor	Fair	Fair
St. John's Elementary School- Building A	N/A	N/A	Fair	Fair	Fair	Fair	Good
St. John's Elementary School- Building B	Very Good	N/A	Good	Fair	Fair	Fair	Good
St. John's Elementary School- Building C	N/A	Good	Fair	Fair	Fair	Fair	Good
Thornwell School for the Arts- Building 3	N/A	N/A	Good	Poor	Poor	Poor	Fair

Name of School or Building	Auditorium/ Multipurpose Area Condition	Kitchen Condition	Toilet Room Condition	Administration HVAC	Classroom HVAC	Other HVAC	Main Electrical Entrance
Thornwell School for the Arts- Building 5	N/A	Fair	Good	Poor	Poor	Poor	Fair
Thornwell School for the Arts- Gymnasium	N/A	N/A	Good	Poor	Poor	Poor	Fair
Thornwell School for the Arts- Main Building	N/A	N/A	Good	Poor	Poor	Poor	Fair
Washington Street Elementary School	N/A	Good	Good	Good	Good	Good	Good
West Hartsville Elementary School	N/A	Good	Good	Fair	Fair	Fair	Poor
Brunson-Dargan Elementary School	N/A	Good	Fair	Fair	Fair	Fair	Good
Spaulding Middle School	N/A	Good	Good	Good	Good	Good	Good

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Brockington Elementary Magnet School	Good	Good	Good	Good	Good
Brunson-Dargan Elementary School- Library Building	Good	Good	Good	New/Less than Not Operational year	Fair
Cain Elementary School- Building 1	Good	Good	Good	New/Less than Not Operational year	Good
Cain Elementary School- Building 2	Fair	Fair	Fair	New/Less than Not Operational year	Fair
Cain Elementary School- Building 3	Good	Good	Good	New/Less than Not Operational year	Good
Cain Elementary School- Building 4	Good	Good	Very Good	New/Less than Not Operational year	Very Good
Carolina Elementary School	Good	Good	Good	Good	Good
Darlington County Adult Education Building	Fair	Fair	Fair	Good	Good
Darlington County Institute of Technology	Good	Very Good	Good	Good	Good

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Darlington County Intervention School	Fair	Fair	Fair	Very Good	Very Good
Darlington High School - Main Building	Fair	Fair	Fair	Good	Fair
Darlington High School- 9th Grade Building	Fair	Fair	Fair	New/Less than Not Operational year	Fair
Darlington High School- Band Building	Fair	Fair	Fair	Good	Fair
Darlington High School- Cafeteria Building	Fair	Fair	Fair	Good	Fair
Darlington High School- Gym	Good	Good	Good	Good	Good
Darlington High School- ROTC Building	Fair	Fair	Fair	Fair	Fair
Darlington Middle School	Good	Very Good	Good	Very Good	Good
Hartsville High School Building 1	Fair	Fair	Fair	Very Good	Fair

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Hartsville High School Building 2	Fair	Fair	Fair	Very Good	Fair
Hartsville High School Building 3	Fair	Fair	Fair	Very Good	Fair
Hartsville High School Building 4	Fair	Fair	Fair	Very Good	Fair
Hartsville High School Building 5	Fair	Fair	Fair	Very Good	Fair
Hartsville High School Building 6, Cafeteria	Fair	Fair	Fair	Very Good	Fair
Hartsville High School Building 7	Fair	Fair	Fair	Very Good	Fair
Hartsville High School Main Office	Fair	Fair	Fair	Very Good	Fair
Hartsville High School, Art Building	Fair	Fair	Fair	Very Good	Fair
Hartsville High School, Band Building	Fair	Fair	Fair	Very Good	Fair

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Hartsville High School, Locker Room	Fair	Fair	Fair	Very Good	Fair
Hartsville High School, Main Gym	Very Good	Very Good	Very Good	Very Good	Very Good
Hartsville High School, Ulmer Gym	Fair	Fair	Fair	Very Good	Fair
Hartsville Middle School	Very Good	Very Good	Good	Good	Good
Lamar Elementary School-Building 1	Good	Good	Good	Good	Good
Lamar Elementary School-Building 2	Good	Good	Good	Good	Good
Lamar High School	Good	Good	Good	Very Good	Good
Mayo High School	Fair	Fair	Fair	Good	Good
Mayo High School Annex Building	Fair	Fair	Fair	Good	Good

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Mayo High School Building 3	Fair	Fair	Fair	Good	Fair
Mayo High School Building 4 Cafeteria	Fair	Fair	Fair	Good	Fair
Mayo High School Building 5	Fair	Fair	Fair	Fair	Fair
North Hartsville Elementary School- Building 1 and 2	Good	Good	Good	Good	Good
North Hartsville Elementary School- Building 3	Good	Good	Good	Good	Good
Pate Elementary School- Building 1	Good	Good	Good	Good	Fair
Pate Elementary School- Building 2	Good	Good	Good	Good	Good
Rosenwald Elementary/Middle School	Good	Good	Good	Good	Good
Rosenwald Elementary/Middle School- Building 2	Good	Good	Good	Good	Good

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Rosenwald Elementary/Middle School- Main Building	Good	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 1	Good	Good	Good	Good	Good
Southside Early Childhood Education Center- Building 2	Good	Good	Good	New/Less than Not Operational year	Good
Southside Early Childhood Education Center- Building 3	Good	Good	Good	New/Less than Not Operational year	Very Good
Spaulding Elementary School	Fair	Fair	Good	New/Less than Not Operational year	Good
St. John's Elementary School-Building A	Good	Good	Good	Good	Good
St. John's Elementary School-Building B	Good	Good	Good	Good	Good
St. John's Elementary School-Building C	Fair	Fair	Good	Good	Good
Thornwell School for the Arts-Building 3	Fair	Good	Good	Good	Good

Name of School or Building	Electrical Distribution	Lighting	Plumbing	Fire Alarm	Fire Sprinkler
Thornwell School for the Arts-Building 5	Fair	Good	Good	Good	Good
Thornwell School for the Arts-Gymnasium	Fair	Good	Good	Good	Good
Thornwell School for the Arts-Main Building	Fair	Fair	Good	Good	Good
Washington Street Elementary School	Good	Good	Good	Good	Good
West Hartsville Elementary School	Fair	Fair	Good	Good	Good
Brunson-Dargan Elementary School	Good	Good	Good	New/Less than Not Operational year	Good
Spaulding Middle School	Good	Good	Good	Very Good	Good

Name of School or Building	Comments on building exterior
Brockington Elementary Magnet School	
Brunson-Dargan Elementary School- Library Building	Outdoor walkways leak when there is any kind of rainstorm.
Cain Elementary School- Building 1	
Cain Elementary School- Building 2	
Cain Elementary School- Building 3	
Cain Elementary School- Building 4	
Carolina Elementary School	
Darlington County Adult Education Building	
Darlington County Institute of Technology	

Name of School or Building	Comments on building exterior
Darlington County Intervention School	Breezeways have poor drainage and become slippery when wet.
Darlington High School - Main Building	
Darlington High School- 9th Grade Building	
Darlington High School- Band Building	
Darlington High School- Cafeteria Building	
Darlington High School- Gym	
Darlington High School- ROTC Building	
Darlington Middle School	
Hartsville High School Building 1	

Name of School or Building	Comments on building exterior
Hartsville High School Building 2	
Hartsville High School Building 3	
Hartsville High School Building 4	
Hartsville High School Building 5	
Hartsville High School Building 6, Cafeteria	
Hartsville High School Building 7	New roof currently being installed. Unidentified wires hanging on the outside of the building.
Hartsville High School Main Office	
Hartsville High School, Art Building	
Hartsville High School, Band Building	

Name of School or Building	Comments on building exterior
Hartsville High School, Locker Room	
Hartsville High School, Main Gym	
Hartsville High School, Ulmer Gym	
Hartsville Middle School	
Lamar Elementary School-Building 1	
Lamar Elementary School-Building 2	
Lamar High School	
Mayo High School	
Mayo High School Annex Building	Several leaks in the roof.

Name of School or Building	Comments on building exterior
Mayo High School Building 3	
Mayo High School Building 4 Cafeteria	
Mayo High School Building 5	
North Hartsville Elementary School- Building 1 and 2	
North Hartsville Elementary School- Building 3	
Pate Elementary School- Building 1	
Pate Elementary School- Building 2	
Rosenwald Elementary/Middle School	
Rosenwald Elementary/Middle School- Building 2	

Name of School or Building	Comments on building exterior
Rosenwald Elementary/Middle School- Main Building	
Southside Early Childhood Education Center- Building 1	
Southside Early Childhood Education Center- Building 2	
Southside Early Childhood Education Center- Building 3	
Spaulding Elementary School	
St. John's Elementary School- Building A	
St. John's Elementary School- Building B	
St. John's Elementary School- Building C	
Thornwell School for the Arts- Building 3	

Name of School or Building	Comments on building exterior
Thornwell School for the Arts-Building 5	
Thornwell School for the Arts-Gymnasium	
Thornwell School for the Arts-Main Building	
Washington Street Elementary School	
West Hartsville Elementary School	
Brunson-Dargan Elementary School	Outdoor walkways leak whenever it rains.
Spaulding Middle School	

Name of School or Building	Comments on building accessibility
Brockington Elementary Magnet School	
Brunson-Dargan Elementary School- Library Building	
Cain Elementary School- Building 1	
Cain Elementary School- Building 2	
Cain Elementary School- Building 3	
Cain Elementary School- Building 4	
Carolina Elementary School	
Darlington County Adult Education Building	Gymnasium is being leased by the city of Darlington and is not used by the Adult Education building.
Darlington County Institute of Technology	

Name of School or Building	Comments on building accessibility
Darlington County Intervention School	
Darlington High School - Main Building	
Darlington High School- 9th Grade Building	
Darlington High School- Band Building	
Darlington High School- Cafeteria Building	
Darlington High School- Gym	
Darlington High School- ROTC Building	
Darlington Middle School	
Hartsville High School Building 1	

Name of School or Building	Comments on building accessibility
Hartsville High School Building 2	
Hartsville High School Building 3	
Hartsville High School Building 4	
Hartsville High School Building 5	
Hartsville High School Building 6, Cafeteria	
Hartsville High School Building 7	
Hartsville High School Main Office	
Hartsville High School, Art Building	
Hartsville High School, Band Building	

Name of School or Building	Comments on building accessibility
Hartsville High School, Locker Room	
Hartsville High School, Main Gym	
Hartsville High School, Ulmer Gym	
Hartsville Middle School	
Lamar Elementary School-Building 1	
Lamar Elementary School-Building 2	
Lamar High School	
Mayo High School	
Mayo High School Annex Building	

Name of School or Building	Comments on building accessibility
Mayo High School Building 3	
Mayo High School Building 4 Cafeteria	
Mayo High School Building 5	
North Hartsville Elementary School- Building 1 and 2	
North Hartsville Elementary School- Building 3	
Pate Elementary School- Building 1	
Pate Elementary School- Building 2	
Rosenwald Elementary/Middle School	
Rosenwald Elementary/Middle School- Building 2	

Name of School or Building	Comments on building accessibility
Rosenwald Elementary/Middle School- Main Building	
Southside Early Childhood Education Center- Building 1	
Southside Early Childhood Education Center- Building 2	
Southside Early Childhood Education Center- Building 3	
Spaulding Elementary School	
St. John's Elementary School- Building A	
St. John's Elementary School- Building B	
St. John's Elementary School- Building C	
Thornwell School for the Arts- Building 3	

Name of School or Building	Comments on building accessibility
Thornwell School for the Arts-Building 5	
Thornwell School for the Arts-Gymnasium	
Thornwell School for the Arts-Main Building	
Washington Street Elementary School	
West Hartsville Elementary School	
Brunson-Dargan Elementary School	
Spaulding Middle School	

Name of School or Building	Comments on building interior finishes
Brockington Elementary Magnet School	Minor leaks in part of the ceiling and in the cafeteria during a heavy rainstorm.
Brunson-Dargan Elementary School- Library Building	Leaks in rooms #32 and #37 as well as several missing ceiling tiles.
Cain Elementary School- Building 1	
Cain Elementary School- Building 2	
Cain Elementary School- Building 3	
Cain Elementary School- Building 4	
Carolina Elementary School	Leak in the library that was being fixed during the time of the inspection.
Darlington County Adult Education Building	
Darlington County Institute of Technology	

Name of School or Building	Comments on building interior finishes
Darlington County Intervention School	
Darlington High School - Main Building	Several missing ceiling tiles.
Darlington High School- 9th Grade Building	Several wet marks on ceiling indicating potential leaking problems.
Darlington High School- Band Building	
Darlington High School- Cafeteria Building	Several wet spots in kitchen ceiling but no reported leaking.
Darlington High School- Gym	
Darlington High School- ROTC Building	Leak in the janitor closet.
Darlington Middle School	
Hartsville High School Building 1	Bad leaks in rooms #112 and #118 as well as the second floor hallway.

Name of School or Building	Comments on building interior finishes
Hartsville High School Building 2	
Hartsville High School Building 3	
Hartsville High School Building 4	
Hartsville High School Building 5	Several bad leaks in main hallway of the building with ceiling tiles constantly needing to be replaced.
Hartsville High School Building 6, Cafeteria	
Hartsville High School Building 7	Bad leaks inside the building.
Hartsville High School Main Office	
Hartsville High School, Art Building	
Hartsville High School, Band Building	

Name of School or Building	Comments on building interior finishes
Hartsville High School, Locker Room	
Hartsville High School, Main Gym	
Hartsville High School, Ulmer Gym	
Hartsville Middle School	
Lamar Elementary School-Building 1	Small leaks in rooms #114 and #116.
Lamar Elementary School-Building 2	Small leaks in the physical therapy room.
Lamar High School	Leaks in the cafeteria when it rains.
Mayo High School	Leak in room #209 and the girls bathroom on the second floor.
Mayo High School Annex Building	

Name of School or Building	Comments on building interior finishes
Mayo High School Building 3	Leak in room #313.
Mayo High School Building 4 Cafeteria	
Mayo High School Building 5	
North Hartsville Elementary School- Building 1 and 2	
North Hartsville Elementary School- Building 3	Kitchen dish sink is leaking as well as a few more minor leaks in the cafeteria ceiling.
Pate Elementary School- Building 1	
Pate Elementary School- Building 2	
Rosenwald Elementary/Middle School	
Rosenwald Elementary/Middle School- Building 2	

Name of School or Building	Comments on building interior finishes
Rosenwald Elementary/Middle School- Main Building	Bathroom in the kitchen does not work.
Southside Early Childhood Education Center- Building 1	
Southside Early Childhood Education Center- Building 2	
Southside Early Childhood Education Center- Building 3	
Spaulding Elementary School	
St. John's Elementary School- Building A	
St. John's Elementary School- Building B	Minor leaks in 2nd floor hallway.
St. John's Elementary School- Building C	
Thornwell School for the Arts- Building 3	

Name of School or Building	Comments on building interior finishes
Thornwell School for the Arts-Building 5	Oven in the cafeteria does not work properly and there is a broken mixer according to the kitchen staff.
Thornwell School for the Arts-Gymnasium	
Thornwell School for the Arts-Main Building	Leak in the bookkeeper's office which has been going on for 3+ years.
Washington Street Elementary School	
West Hartsville Elementary School	Small leak in the PE room.
Brunson-Dargan Elementary School	
Spaulding Middle School	Dishwasher in kitchen does not work.

Name of School or Building	Comments on MEP
Brockington Elementary Magnet School	
Brunson-Dargan Elementary School- Library Building	
Cain Elementary School- Building 1	Reported problems with the heat in the kitchen.
Cain Elementary School- Building 2	
Cain Elementary School- Building 3	
Cain Elementary School- Building 4	
Carolina Elementary School	
Darlington County Adult Education Building	
Darlington County Institute of Technology	

Name of School or Building	Comments on MEP
Darlington County Intervention School	Storage rooms have poor ventilation.
Darlington High School - Main Building	Water will not drain out of janitor closets.
Darlington High School- 9th Grade Building	
Darlington High School- Band Building	
Darlington High School- Cafeteria Building	
Darlington High School- Gym	
Darlington High School- ROTC Building	
Darlington Middle School	
Hartsville High School Building 1	

Name of School or Building	Comments on MEP
Hartsville High School Building 2	
Hartsville High School Building 3	
Hartsville High School Building 4	
Hartsville High School Building 5	
Hartsville High School Building 6, Cafeteria	
Hartsville High School Building 7	
Hartsville High School Main Office	
Hartsville High School, Art Building	
Hartsville High School, Band Building	

Name of School or Building	Comments on MEP
Hartsville High School, Locker Room	
Hartsville High School, Main Gym	
Hartsville High School, Ulmer Gym	Intercom system does not work.
Hartsville Middle School	Electrical closet in 6th grade hallway gets very hot and the door needs to be kept open to avoid overheating.
Lamar Elementary School-Building 1	
Lamar Elementary School-Building 2	
Lamar High School	HVAC is in poor condition.
Mayo High School	
Mayo High School Annex Building	

Name of School or Building	Comments on MEP
Mayo High School Building 3	
Mayo High School Building 4 Cafeteria	Poor ventilation in the kitchen area.
Mayo High School Building 5	
North Hartsville Elementary School- Building 1 and 2	
North Hartsville Elementary School- Building 3	
Pate Elementary School- Building 1	
Pate Elementary School- Building 2	
Rosenwald Elementary/Middle School	
Rosenwald Elementary/Middle School- Building 2	

Name of School or Building	Comments on MEP
Rosenwald Elementary/Middle School- Main Building	
Southside Early Childhood Education Center- Building 1	
Southside Early Childhood Education Center- Building 2	
Southside Early Childhood Education Center- Building 3	
Spaulding Elementary School	The heat throughout the building is inconsistent.
St. John's Elementary School- Building A	
St. John's Elementary School- Building B	Occasional heat problems.
St. John's Elementary School- Building C	
Thornwell School for the Arts- Building 3	HVAC does not function properly.

Name of School or Building	Comments on MEP
Thornwell School for the Arts-Building 5	HVAC does not function properly.
Thornwell School for the Arts-Gymnasium	HVAC not functioning properly.
Thornwell School for the Arts-Main Building	HVAC does not maintain proper temperatures in the building.
Washington Street Elementary School	
West Hartsville Elementary School	Old loose wires hanging in the electrical closet.
Brunson-Dargan Elementary School	
Spaulding Middle School	

Name of School or Building	Comments on building life safety and security
Brockington Elementary Magnet School	
Brunson-Dargan Elementary School- Library Building	
Cain Elementary School- Building 1	Burglar alarm sometimes goes off unexpectedly even when there is no reported break in.
Cain Elementary School- Building 2	
Cain Elementary School- Building 3	
Cain Elementary School- Building 4	
Carolina Elementary School	
Darlington County Adult Education Building	
Darlington County Institute of Technology	

Name of School or Building	Comments on building life safety and security
Darlington County Intervention School	
Darlington High School - Main Building	
Darlington High School- 9th Grade Building	
Darlington High School- Band Building	
Darlington High School- Cafeteria Building	
Darlington High School- Gym	
Darlington High School- ROTC Building	
Darlington Middle School	
Hartsville High School Building 1	

Name of School or Building	Comments on building life safety and security
Hartsville High School Building 2	
Hartsville High School Building 3	
Hartsville High School Building 4	
Hartsville High School Building 5	
Hartsville High School Building 6, Cafeteria	
Hartsville High School Building 7	
Hartsville High School Main Office	
Hartsville High School, Art Building	
Hartsville High School, Band Building	

Name of School or Building	Comments on building life safety and security
Hartsville High School, Locker Room	
Hartsville High School, Main Gym	
Hartsville High School, Ulmer Gym	
Hartsville Middle School	
Lamar Elementary School-Building 1	
Lamar Elementary School-Building 2	
Lamar High School	
Mayo High School	
Mayo High School Annex Building	

Name of School or Building	Comments on building life safety and security
Mayo High School Building 3	
Mayo High School Building 4 Cafeteria	
Mayo High School Building 5	
North Hartsville Elementary School- Building 1 and 2	
North Hartsville Elementary School- Building 3	
Pate Elementary School- Building 1	
Pate Elementary School- Building 2	
Rosenwald Elementary/Middle School	
Rosenwald Elementary/Middle School- Building 2	

Name of School or Building	Comments on building life safety and security
Rosenwald Elementary/Middle School- Main Building	
Southside Early Childhood Education Center- Building 1	
Southside Early Childhood Education Center- Building 2	
Southside Early Childhood Education Center- Building 3	
Spaulding Elementary School	
St. John's Elementary School- Building A	
St. John's Elementary School- Building B	
St. John's Elementary School- Building C	
Thornwell School for the Arts- Building 3	

Name of School or Building	Comments on building life safety and security
Thornwell School for the Arts-Building 5	
Thornwell School for the Arts-Gymnasium	
Thornwell School for the Arts-Main Building	
Washington Street Elementary School	
West Hartsville Elementary School	
Brunson-Dargan Elementary School	
Spaulding Middle School	

Name of School or Building	
Brockington Elementary Magnet School	
Brunson-Dargan Elementary School- Library Building	
Cain Elementary School- Building 1	
Cain Elementary School- Building 2	
Cain Elementary School- Building 3	
Cain Elementary School- Building 4	
Carolina Elementary School	
Darlington County Adult Education Building	
Darlington County Institute of Technology	

Name of School or Building	
Darlington County Intervention School	
Darlington High School - Main Building	
Darlington High School- 9th Grade Building	
Darlington High School- Band Building	
Darlington High School- Cafeteria Building	
Darlington High School- Gym	
Darlington High School- ROTC Building	
Darlington Middle School	
Hartsville High School Building 1	

Name of School or Building	
Hartsville High School Building 2	
Hartsville High School Building 3	
Hartsville High School Building 4	
Hartsville High School Building 5	
Hartsville High School Building 6, Cafeteria	
Hartsville High School Building 7	
Hartsville High School Main Office	
Hartsville High School, Art Building	
Hartsville High School, Band Building	

Name of School or Building	
Hartsville High School, Locker Room	
Hartsville High School, Main Gym	
Hartsville High School, Ulmer Gym	
Hartsville Middle School	
Lamar Elementary School-Building 1	
Lamar Elementary School-Building 2	
Lamar High School	
Mayo High School	
Mayo High School Annex Building	

Name of School or Building	
Mayo High School Building 3	
Mayo High School Building 4 Cafeteria	
Mayo High School Building 5	
North Hartsville Elementary School- Building 1 and 2	
North Hartsville Elementary School- Building 3	
Pate Elementary School- Building 1	
Pate Elementary School- Building 2	
Rosenwald Elementary/Middle School	
Rosenwald Elementary/Middle School- Building 2	

Name of School or Building	
Rosenwald Elementary/Middle School- Main Building	
Southside Early Childhood Education Center- Building 1	
Southside Early Childhood Education Center- Building 2	
Southside Early Childhood Education Center- Building 3	
Spaulding Elementary School	
St. John's Elementary School- Building A	
St. John's Elementary School- Building B	
St. John's Elementary School- Building C	
Thornwell School for the Arts- Building 3	

Name of School or Building	
Thornwell School for the Arts-Building 5	
Thornwell School for the Arts-Gymnasium	
Thornwell School for the Arts-Main Building	
Washington Street Elementary School	
West Hartsville Elementary School	
Brunson-Dargan Elementary School	
Spaulding Middle School	